



**HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST**

**CARGILL**  
**191 PORTLAND PT. ROAD**

**LANSING, NY** NO ZIP PROVIDED

**Spill Number: 9102851**

**Close Date: 12/08/1993**

ADDRESS CHANGE INFORMATION  
 Revised street: 191 PORTLAND POINT RD  
 Revised zip code: 14882

Source of Spill: COMMERCIAL/INDUSTRIAL  
 Notifier Type: Responsible Party  
 Caller Name: KEN GRIMM  
 DEC Investigator: ROMOCKI

Spiller: CARGILL INC.  
 Notifier Name:  
 Caller Agency: CARGILL INC.  
 Contact for more spill info:

Spiller Phone: (607) 533-4221  
 Notifier Phone:  
 Caller Phone: (607) 533-4221  
 Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.  
 Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
06/11/1991	12/08/1993	EQUIPMENT FAILURE	UNKNOWN	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	10.00	GALLONS	3.00	GALLONS	

**Caller Remarks:**

**SHEEN DISCOVERED IN LAKE BELIEVED TO BE COMING FROM ABANDONNED BUILDING.**

**DEC Investigator Remarks:**

Prior to Sept, 2004 data translation this spill Lead\_DEC Field was MR 07/05/91: PRODUCT I.D. AS LUBE OIL.APEARS TO BE COMING FROM HOIST HOUSE WHERE THIS PRODUCT IS USED. CONCRETE TANK IN FRINT OF HOIST HOUSE WAS REMOVED AND **FREE PRODUCT WAS FOUND AT THE EXCAVATION.MORE TO FOLLOW.** 07/26/91: VISITED SITE WITH HARRY WARNER, DON FLETCHER, CHARLIE GAYNOR. INSPECTED THE FORMER SEPTIC TANK SITE;**OIL STILL SLOWLY ENTERING THE HOLE. OIL ALSO STILL LEAVING THE HILLSIDE ON GROUNDWATER STREAM.**FOLLOW. 01/28/92: REC'D REPORT FROMCARGILL WITH ANALYSIS OF GROUND WATER SAMPLES FROM WELLS DRILLED. REFERRED REPORT TO J.MOSKOWITZ.



**HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST**

**CARGILL INC. PIPELINE  
EAST SHORE OF CAYUGA LAKE**

**ITHACA (LANSING), NY** NO ZIP PROVIDED

**Spill Number: 8807513**

**Close Date: 10/23/2003**

ADDRESS CHANGE INFORMATION  
Revised street: PORTLAND POINT RD  
Revised zip code: 14882

Source of Spill: UNKNOWN  
Notifier Type: Responsible Party  
Caller Name: KEN GRIMM  
DEC Investigator: CSCUIPLY

Spiller: CARGILL INC.  
Notifier Name:  
Caller Agency: CARGILL INC.  
Contact for more spill info:

Spiller Phone: (607) 533-4221  
Notifier Phone:  
Caller Phone: (607) 533-4221  
Contact Person Phone:

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors),  
contamination of drinking water supplies, or significant release to surface waters.  
Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
12/12/1988		UNKNOWN	NO		NO	

  

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0.00	POUNDS	0.00	POUNDS	GROUNDWATER

**Caller Remarks:**

**DIGGING IN AREA NEAR UNDERGROUND PIPELINE. MADE A DRENCH TO COLLECT 300 TO 400 GALLONS OF WATER. SHEEN ON TOP OF WATER 1/8 THICK.**

**DEC Investigator Remarks:**

Prior to Sept, 2004 data translation this spill Lead\_DEC Field was CC 01/19/89: **OIL PICKED UP.** WATER TESTED AND DISCHARGED TO A HOLDING POND.



**HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST**

**CARGILL**  
**191 PORTLAND POINT ROAD**

**LANSING, NY** NO ZIP PROVIDED

**Spill Number: 8810106**

**Close Date: 10/23/2003**

ADDRESS CHANGE INFORMATION  
 Revised street: 191 PORTLAND POINT RD  
 Revised zip code: 14882

Source of Spill: COMMERCIAL/INDUSTRIAL  
 Notifier Type: Responsible Party  
 Caller Name: CHARLES VONDREUSCHE  
 DEC Investigator: CSCUIPLY

Spiller: CARGILL  
 Notifier Name:  
 Caller Agency: CARGILL  
 Contact for more spill info:

Spiller Phone: (607) 533-4221  
 Notifier Phone:  
 Caller Phone: (607) 533-4221  
 Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
03/30/1989		HOUSEKEEPING	NO		NO	
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0.00	POUNDS	0.00	POUNDS	SURFACE WATER

**Caller Remarks:**

**RUN OFF FROM PAVEMENT.** DRIPPING FROM TRUCKS THAT WERE LOADING SALT. **BOOM WAS PLACED AT MOUTH OF LAKE.**

**DEC Investigator Remarks:**

Prior to Sept, 2004 data translation this spill Lead\_DEC Field was CC 10/03/95: This is additional information about material spilled from the translation of the old spill file: **MOTOR & HYDRO OIL.**



**HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST**

**CARGILL DEICING TECH**  
**191 PORTLAND POINT P**

**LANSING, NY** NO ZIP PROVIDED

**Spill Number: 1404403**

**Close Date: 07/23/2014**

ADDRESS CHANGE INFORMATION  
 Revised street: 191 PORTLAND POINT RD  
 Revised zip code: 14882

Source of Spill: COMMERCIAL/INDUSTRIAL  
 Notifier Type: Other  
 Caller Name:  
 DEC Investigator: menash

Spiller: MALLORY APPERSON – CARGILL DEICING TECH  
 Notifier Name:  
 Caller Agency:  
 Contact for more spill info: MALLORY APPERSON

Spiller Phone:  
 Notifier Phone:  
 Caller Phone:  
 Contact Person Phone: (607) 533-3727

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non-petroleum/non-hazardous spills.  
 Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
07/23/2014		EQUIPMENT FAILURE	NO		NO	
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
OTHER	OTHER	200.00	GALLONS	0.00	GALLONS	SOIL SURFACE WATER

**Caller Remarks:**

drain leaking into culvert that enters the lake, water diverted to mine, pump into stream to reclaim product from lake

**DEC Investigator Remarks:**

Turned Spill over to Fred Gillett, Water Engineer who oversees Cargill SPDES Permit.



**HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST**

**CAYUGA MINE**  
**191 PORTLAND POINT RD**

**LANSING, NY** NO ZIP PROVIDED

**Spill Number: 0813014**

**Close Date: 03/24/2009**

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE  
 Revised zip code: 14882

Source of Spill: COMMERCIAL/INDUSTRIAL  
 Notifier Type: Responsible Party  
 Caller Name:  
 DEC Investigator: MJROMOCK

Spiller: WILLIAM GRACON – CARGILL  
 Notifier Name:  
 Caller Agency:  
 Contact for more spill info: WILLIAM GRACON

Spiller Phone:  
 Notifier Phone:  
 Caller Phone:  
 Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.

Class: Willing RP – No DEC Field Response – Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
03/04/2009		EQUIPMENT FAILURE	NO		NO	
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
OTHER	OTHER	30.00	GALLONS	0.00	GALLONS	SOIL SURFACE WATER

Caller Remarks:

Caller states a pipe failure caused material to spill onto the soil on the bank of above lake. Spill is being contained and cleanup is ongoing.

DEC Investigator Remarks:

Pipe fitting failed causing leak. Repair made and cleanup effected.



**HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST**

**CARGILL**  
**191 PORTLAND POINT RD**

**LANSING, NY** 14882

**Spill Number: 0808854**

**Close Date: 11/06/2008**

**ADDRESS CHANGE INFORMATION**

Revised street: NO CHANGE  
 Revised zip code: NO CHANGE

Source of Spill: COMMERCIAL/INDUSTRIAL  
 Notifier Type: Responsible Party  
 Caller Name:  
 DEC Investigator: KCKEMP

Spiller: GREG ZACEK – CARGILL DE-ICING TECH  
 Notifier Name:  
 Caller Agency:  
 Contact for more spill info: GREG ZACEK

Spiller Phone:  
 Notifier Phone:  
 Caller Phone:  
 Contact Person Phone: (607) 228-7028

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non-petroleum/non-hazardous spills.  
 Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
11/05/2008		HUMAN ERROR	NO			
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
OTHER	OTHER	25.00	GALLONS	0.00	GALLONS	SOIL

**Caller Remarks:**

**CALLER STATES THAT ABOUT 25 GALLONS OF PRODUCT SPILLED TO TRAIN TRACKS WHEN THEY WERE FILLING A TANK CAR, A VALVE WAS LEFT OPEN. CLEAN UP IS IN PROGRESS.**

**DEC Investigator Remarks:**

**1% MgCl solution spilled to soil when moved rail car with open valve. Spill not fully contained in track pan between rails. Cargill to excavate affected soil. M Romocki to inspect site 11/6/08. MgCl is NOT CBS.**

11/06/08 – Inspected site . Met with Bill Gracon of Cargill. Cleanup sufficient.



**HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST**

**CARGILL INC**  
**191 PORTLAND POINT RD**

**LANSING, NY** NO ZIP PROVIDED

**Spill Number: 0203724**

**Close Date: 07/09/2002**

ADDRESS CHANGE INFORMATION  
 Revised street: NO CHANGE  
 Revised zip code: 14882

Source of Spill: COMMERCIAL/INDUSTRIAL

Spiller: STEVE HORNE – CARGILL INC

Spiller Phone: (607) 533-4221  
 ext: 533

Notifier Type: Responsible Party  
 Caller Name: STEVE HORNE

Notifier Name:  
 Caller Agency: CARGILL INC

Notifier Phone:  
 Caller Phone: (607) 533-4221  
 ext: 353

DEC Investigator: CLWARNER

Contact for more spill info: STEVE HORNE

Contact Person Phone: (607) 533-4221  
 ext: 353

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors),  
 contamination of drinking water supplies, or significant release to surface waters.  
 Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended
07/09/2002		EQUIPMENT FAILURE	NO	NO

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
ZINC SULFATE	HAZARDOUS MATERIAL	0.00	GALLONS	0.00	GALLONS	SURFACE WATER

**Caller Remarks:**

poss leak in line in water treatment plant that caused approx 2 oz's of product to spil into out fault which leads to lake –  
 caller states lake has milky white sheen and has been dyked off

**DEC Investigator Remarks:**

Prior to Sept, 2004 data translation this spill Lead DEC Field was CWS 7-9-02 VISITED SITE. SPOKE WITH STEVE HORNE. MATERIAL  
 ESCAPED THRU CRACK IN FLOOR AND ENTERED FOUNDATION DRAIN. CARGILL DYKED DRAINAGE DITCH AND PUMPED MATERIAL INTO TRUCK. SMALL  
 AMOUNT REACHED LAKE. LAKE APPEARED CLEAN AT TIME OF VISIT. CARGILL TO REPAIR FLOOR TO PREVENT FURTHER DISCHARGES. NO FURTHER  
 ACTON.



**HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST**

**CARGILL INC. - TANK REMOVA**  
**191 PORTLAND PT. RD.**

**LANSING, NY** NO ZIP PROVIDED

**Spill Number: 9402846**

**Close Date: 10/31/2003**

ADDRESS CHANGE INFORMATION  
 Revised street: 191 PORTLAND POINT RD  
 Revised zip code: 14882

Source of Spill: COMMERCIAL/INDUSTRIAL  
 Notifier Type: Responsible Party  
 Caller Name: KEN GRIMM  
 DEC Investigator: ROMOCKI

Spiller: CARGILL INC.  
 Notifier Name:  
 Caller Agency: CARGILL INC.  
 Contact for more spill info:

Spiller Phone: (607) 533-4221  
 Notifier Phone:  
 Caller Phone: (607) 533-4221  
 Contact Person Phone:

Category: Possible petroleum release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters, known releases with no potential for damage, or non-petroleum/non-hazardous spills.  
 Class: Willing RP - No DEC Field Response - Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards	Penalty Recommended		
05/26/1994		HUMAN ERROR	NO	NO		
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
The following material was dropped or revised by the NYS DEC. <b>DIESEL</b>	UNKNOWN	15.00	GALLONS	0.00	GALLONS	

**Caller Remarks:**

**SOME CONTAMINATED SOIL OBSERVED DURING TANK REMOVAL.** ASSUMED IT CAME FROM OVERFILLS.

**DEC Investigator Remarks:**

Prior to Sept, 2004 data translation this spill Lead\_DEC Field was MR 05/27/94: CONTAMINATED SOIL BEING EXCAVATED FOR DISPOSAL BY EPS. GAYNOR DOIMG SITE ASSESSMENT.